



Firmware Update for Certain Pioneer In-Dash AV Receivers

Jan 23rd, 2026

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only the following Pioneer In-Dash AV Receivers sold in Singapore, Malaysia, Indonesia, Philippines, Sri Lanka, Vietnam, Thailand, Cambodia, Myanmar and Laos**. Installation on any other product could cause irreversible damage.

DMH-ZF9650BT

This firmware update corrects the following matter.

- Fixed popping sound on boot up when radio source is selected.

To perform this update, the following items are needed:

- Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 512 MB or larger in capacity, formatted to FAT32 or NTFS.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about fifteen minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: :
<https://pioneercarentertainment.com/software-and-firmware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact the nearest Pioneer Customer Service at your country. You can refer to <https://pioneercarentertainment.com/service-centres/> for more information.

Sincerely,

Pioneer Electronics AsiaCentre Pte. Ltd.