



## Firmware Update (version 8.50) for Pioneer Multimedia Receivers

August 26, 2016

### Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.50) for the current lineup of Pioneer DVD in-dash receivers. **This firmware update is only for the following Pioneer DVD in-dash Receiver models, AVH-X1750DVD, AVH-X2750BT, AVH-X4750DVD, AVH-XL4750DVD, AVH-X5750BT, AVH-XL5750BT, AVH-X6750DVD, and AVH-X7750BT, sold in Indonesia, Malaysia, Philippines, Singapore, Sri Lanka, Thailand, and Vietnam..** Installation on any other product could cause irreversible damage.

This firmware update (version 8.50) contains the following improvements:

- Add 「AppRadioMode Sound」 settings to System Menu
- Fixed incompatibility issues of virtual keyboard with iOS9
- Improvement of connectivity for MirrorLink
- Minor bug fixes

In order to perform this update, the following items are needed:

- Pioneer Multimedia Receiver **AVH-X1750DVD, AVH-X2750BT, AVH-X4750DVD, AVH-XL4750DVD, AVH-X5750BT, AVH-XL5750BT, AVH-X6750DVD or AVH-X7750BT.**
- A blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are attached. Installation of the update should take no more than ten minutes to complete.

### How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:  
<http://www.pioneer.com.sg/sg/support/firmware/index.html/>
2. Transfer the files to the USB storage device for insertion into the Pioneer Multimedia Receiver.

### Questions

If you have any questions, please contact the nearest Pioneer Customer Service at your country. You can refer to [www.pioneer.com.sg/sg/support/service/index.html](http://www.pioneer.com.sg/sg/support/service/index.html) for more information.

Sincerely,

**Pioneer Electronics AsiaCentre**